


AREAS IN RED ARE OVER 30% SLOPE  
NO BUILD AREA



NOTICE: "According to Colorado law you must commence any legal action based upon any defect in this survey within three years after you first discover such defect. In no event, may any action based upon any defect in this survey be commenced more than ten years from the date of the certification shown hereon."

**EMERALD MOUNTAIN  
SURVEYS, INC.**  
P.O. BOX 774812  
STEAMBOAT SPRINGS,  
COLORADO 80477  
970-879-8998  
COPYRIGHT 2022

[www.emeraldmtn.net](http://www.emeraldmtn.net)

## SLOPE ANALYSIS

JLB REPLAT  
HORSEBACK at STAGECOACH  
ROUTT COUNT, COLORADO

This exhibit does not  
represent a monumented  
survey. It is intended only  
to depict the attached  
description.

1-16-2022

3970-1

1" = 100'