




Aspen Heights Subdivision, Filing No. 9

SHEET 1 OF 2



NOTICE: "According to Colorado law you must commence any legal action based upon any defect in this survey within three years after you first discover such defect. In no event, may any action based upon any defect in this survey be commenced more than ten years from the date of the certification shown hereon."



**EMERALD MOUNTAIN
SURVEYS, INC.**

P.O. BOX 774812
STEAMBOAT SPRINGS,
COLORADO 80477
970-879-8998

COPYRIGHT 2021

www.emeraldmtn.net

SLOPE ANALYSIS

BOLA ENTERPRISES, INC.
BOX 773630
STERAMBOAT SPRINGS, CO. 80477

This exhibit does not
represent a monumented
survey. It is intended only
to depict the attached
description.

11-27-2021

3747-2

1" = 250'

Slopes Table				
Number	Minimum Slope	Maximum Slope	Area	Color
1	0.00%	30.00%	8646050.88	
2	31.00%	95.22%	172243.31	

Aspen Heights Subdivision, Filing No. 9

SHEET 2 OF 2

NOTICE: "According to Colorado law you must commence any legal action based upon any defect in this survey within three years after you first discover such defect. In no event, may any action based upon any defect in this survey be commenced more than ten years from the date of the certification shown hereon."

 EMERALD MOUNTAIN SURVEYS, INC. P.O. BOX 774812 STEAMBOAT SPRINGS, COLORADO 80477 970-879-8998 COPYRIGHT 2021 www.emeraldmttn.net	SLOPE ANALYSIS			<i>This exhibit does not represent a monumented survey. It is intended only to depict the attached description.</i>
	BOLA ENTERPRISES, INC. BOX 773630 STERAMBOAT SPRINGS, CO. 80477			
	11-27-2021	3747-2		